# Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC.
Well Operator: EOG RESOURCES, INC.
Well Name: CLARKS CREEK 15-0805H

Field Name: ANTELOPE Well File #: 20602

Date Incident: 9/3/2015 Time Incident: 08:35 Facility ID Number:

County: MCKENZIE Twp: 151 Rng: 94 Sec: 8 Qtr: SE SE

**Location Description:** 

Submitted By: Keith Kallberg Received By:

Contact Person: Keith Kallberg

600 17TH ST STE 1000N DENVER. CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units
2 Barrels 2 Barrels 2 barrels

Brine Other

Oil

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 9/16/2015 Clean Up Concluded: 9/4/2015

Risk Evaluation:

Low

Areal Extent:

N/A

# Potential Environmental Impacts:

Low

# Action Taken or Planned:

Free fluids were removed, the area was flushed, washed/rinsed 2 x with fresh water and dawn soap, fluids removed .

Wastes Disposal Location: Fluids were taken to the Grail SWD

Agencies Involved: MHA & TAT

#### **Updates**

Date: 9/4/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

Release, due to an equipment failure, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.